

plasmabrush® PB3

Operating instructions **PS2000 power supply**



Thank you for buying a **Relyon Plasma** GmbH branded product. To get the best from your machine, please read these instructions carefully.

i Important!
Read these instructions carefully before assembling, installing and starting up the machine!

Always follow the safety instructions! Failure to follow the safety instructions may result in accidents, serious injury and serious damage to the machine.

The PS2000 power supply may only be started up and operated by trained and qualified persons!

Train your staff! The operator / user is responsible for ensuring that personnel have fully understood the operation of the machine and the safety requirements.

© Copyright **Relyon Plasma** GmbH 2024.

All rights reserved.

Text, images and graphics as well as their layout are protected by copyright and other protective laws. Unauthorised copying and distribution of this document and the utilisation and communication of its contents are strictly prohibited unless expressly authorised. Offenders will be held liable for the payment of damages. All rights reserved in the event of the grant of a patent, utility model or design.

Original operating
instructions

1	Safety	4
1.1	Residual risks	4
1.2	Information and obligations for the operator	6
1.3	Intended use	6
1.4	Impermissible operating conditions	6
1.5	Emissions	6
2	Description of machine	7
2.1	Overview of the machine	7
2.2	Installation dimensions	7
2.3	Description and connections	8
2.4	Power connector pin assignment	9
2.5	Pin assignment of emergency stop plug	10
2.6	Pin assignment of CAN bus socket / plug (9-pin sub D socket / plug)	11
2.7	Scope of delivery	11
3	Technical data	12
3.1	Technical data	12
4	Transport / storage	12
5	Unpacking and installation	12
5.1	Unpacking	13
5.2	Installation requirements	13
5.2.1	Installing and starting up one single PS2000	13
5.2.2	Installing and starting up several PS2000s running in parallel	14
6	Special notes on using the plasma process	15
6.1	General description	15
6.2	Carrying out surface treatment	16
6.3	Measures to take after the surface treatment	16
7	Operation	17
7.1	Controls / displays	17
7.2	Switching on and operating the machine	18
7.2.1	Switching on and operating the machine using the "one push start" button	19
7.2.2	Switching on and operating the machine using the 24 V switching signal	19
7.2.3	Switching on and operating the machine with bus communication	19
7.2.4	CANopen object directory for control device	20
7.2.5	Error messages	21
7.2.6	"Burn in" set of parameters	22
7.3	Switching off the machine	22
7.4	Error acknowledgement	22
8	Taking out of service	23
9	Maintenance and cleaning	24
9.1	Maintenance	24
9.2	Cleaning	24
10	Troubleshooting	25
10.1	Overview of faults / errors	25
11	Environment	26
11.1	Disposal	26
12	CE conformity	26
13	Spare parts	26
	Annex: Complete CANopen object directory	27

1 Safety

The PS2000 power supply was designed in accordance with the relevant international standards. However, as with any technical product, hazards may arise if the system is not used properly or is used for purposes other than its intended use.

Working with the PS2000 power supply can be dangerous and may result in serious or fatal injury. It is therefore essential to protect yourself and others.

In addition to the safety instructions in this document, you must also comply with general safety standards.



Caution – Danger!

When working with the machine, please note and observe the safety instructions and requirements in these operating instructions because non-compliance may result in serious or fatal injury.

1.1 Residual risks

This machine has been manufactured in accordance with the current state of the art. However, it is impossible to eliminate residual risks.

Also comply with the information relating to the plasma generator during operation!

Always adhere to the following safety instructions:



Caution – Electrical voltage!

- Danger from high voltage
 - Never reach into the plasma beam of the connected plasma generator.
 - During operation, never touch the workpiece in contact with the plasma beam or the fixture that holds the workpiece.
 - Never touch the connected plasma generator when the system is in operation.
 - Never direct the plasma beam at people or animals.
 - Earth the plasma generator by fitting in a holding fixture.
- Danger: 230 V. If damage is visible on the electrical connection, mains cable or machine:
 - Do not start up the machine.
 - Replace the damaged parts or have them repaired by a qualified person.



Caution – Health hazard!

The machine operates at a high frequency (40 – 65 kHz at the plasma generator).

- As a precaution, persons with a pacemaker or hearing aid should observe the following:
 - Do not use the PS2000 power supply near the pacemaker or hearing aid.
 - Seek medical advice before working near the system.
- In hospitals and similar facilities, it is possible that the operation of the system may impair the function of electrical medical equipment, computer equipment or other equipment (such as ECG systems or PCs).
 - Make sure that the operator of such equipment or systems is aware of this possibility before starting up the machine.



Attention – Emissions!

Dangerous amounts of the reaction gas ozone (O₃) may be produced **at the plasma generator** during machine operation (see the operating instructions for the plasma generator).

- Ozone concentrations of more than 0.2 mg/m³ can occur.
- Note that compliance with national health and safety measures is mandatory when operating the machine.
- Only use the machine in well vented areas or in conjunction with a suitable exhaust system.
- Do not leave the machine running unattended.
- Never point the machine at people during operation.



Tripping hazard!

Lay connection cables such that they do not present a tripping hazard.



Attention – Damage to machine!

The machine may overheat. Do not cover the ventilation slots.

1.2 Information and obligations for the operator

- The system may emit interference.
 - The system has been tested in accordance with EMC legislation.
 - The operator must verify and assure electromagnetic compatibility with other electrical and electronic equipment in the immediate vicinity of the system.
- Ensure that:
 - Operating personnel have read and understood these operating instructions.
 - Anyone working near the machine is made aware of the dangers and is provided with the necessary protective equipment.
 - Installations and repairs are only carried out by qualified persons.
- In particular, make operating personnel aware of the safety instructions in this document.
- Always keep the system in a fully functional condition.
- Any modifications made to the machine will invalidate the operating licence and the warranty. Exception: Such modifications are expressly authorised by the manufacturer.

1.3 Intended use

The PS2000 power supply is only intended for operation of a plasma generator from **Relyon Plasma** GmbH.

The machine is only intended for plasma surface treatment in combination with a suitable plasma generator.

Under no circumstances may the machine be used by non-trained persons.

The machine is intended for installation in a control cabinet.

1.4 Impermissible operating conditions

The machine must not be operated under the following conditions:


- In explosive (EX) zones
- In areas with severe build-up of dust
- In environments where the humidity is too high (see section 3: Technical data)
- At altitudes of more than 2000 m above sea level
- Where there are strong vibrations

1.5 Emissions

The connected plasma generator produces emissions. Please comply with the operating instructions for the plasma generator.

2 Description of machine


2.1 Overview of the machine



Component

PS2000 high-voltage power supply

2.2 Installation dimensions



2.3 Description and connections





Fig.: Diagram of front (top) and rear (bottom)

No.	Component
1	Master switch I/O
2	Momentary contact “High voltage on/off” – “One push start” button with protective flap
3	Display
4	Status LED
5	Ventilation grille with dust filter (class G2 coarse dust filter)
6	GES HB 30 PTFE high-voltage socket for connecting an HVC high-voltage cable
7	230 V AC, 50 Hz power supply socket (for cable type: H05V 3G1.5 CE (3 x 1.5 mm²)) Harting HAN 3
8	Harting HAN M12 emergency stop plug connector
9	Communication (CAN bus) interface (sub D 9-pin) X21, X22
10	Address selector switch for bus communication
11	Earthing connection

2.4 Power connector pin assignment

The power connector comprises the following components:



- 1: Support sleeve
- 2: Panel jack
- 3: Retaining bolt (earthing function)
- 4: PG cable screw connection

Use a H05V 3G1.5 CE (3 x 1.5 mm²) cable to connect the power plug.

The panel jack pin assignment:

PIN 1: L1
PIN 2: N
PIN 3: not connected
PE PIN: PE



Fig.: Pin assignment of mains voltage socket (left) and view of connection side (right)

Only the electricians responsible may connect the wires to the socket (plug assembly)!

2.5 Pin assignment of emergency stop plug

The emergency stop plug supplied consists of 4 individual parts which have to be plugged / screwed together as shown.



Pin assignment of the emergency stop plug:

PIN 1: +24 V output
PIN 2: 0 V / GND output
PIN 3: +24 V input (+/- 10%)
PIN 4: 0 V / GND input



Fig.: Pin assignment of emergency stop plug (left) and view of self-tapping cable guide (right)

The emergency stop circuit consists of a two-channel version. Channel 1: PIN 1 – PIN 3 and channel 2: PIN 2 – PIN 4. So various connections are possible.




Fig.: Emergency stop assignment and various connection options



Attention – Damage to machine!

If using an external voltage (integration in external emergency stop circuit), ensure that the voltage is 24 V DC (+/- 10%) (load: approx. 90 mA).

The output (PIN 1 – 2) of the PS2000 must not be loaded with more than 90 mA under any circumstances.

2.6 Pin assignment of CAN bus socket / plug (9-pin sub D socket / plug)




Fig.: Pin assignment of sub D socket / plug (left) and diagram of both interfaces (right)

2.7 Scope of delivery

The scope of delivery includes the following components:

- PS2000 power supply.
- Power connector for electrical connection of power supply (not mounted).
- Round plug connector for connecting and integrating the PS2000 in internal or external emergency stop circuit (Harting HAN M12).
- Operating instructions.

3 Technical data

3.1 Technical data

Description	Value
Electrical data	
Electrical connection	220 V – 240 V AC / 50 – 60 Hz / max. 6 A
Mains fuse	F1 = 6.3 A / 230 V AC / time lag
Power consumption	≤ 1200 VA
Power loss	Pmax: 450 W
Protection	IP20 acc. to EN 60529
Protection class	Class I acc. to IEC 61140
Operating voltage of plasma generator	<ul style="list-style-type: none">• up to 20 kV Upeak (max. voltage for ignition (briefly))• up to 2 kV RMS (average operating voltage)
Internal F1, F2 fuses	6.3 A / 500 V AC / time lag, SIBA type 189140.6.3
Dimensions	
Weight	18.0 kg; 39.7 lbs
Dimensions	483 x 177 x 423 mm (corresponds to 4 HU); 19" x 6.97" x 16.65" (W x H x D)
Operating conditions	
Air humidity	< 80% rel. (non-condensing)
Temperature	0 – 40°C; 32 – 104°F
Storage conditions	
Air humidity	< 80% rel. (non-condensing)
Temperature	0 – 60°C; 32 – 140°F
Emissions	
• Sound level	< 60 dB(A) at 1 metre away
• Waste heat	Pmax: 450 W

4 Transport / storage

- Store the PS2000 power supply in a dry place. This will prevent the electrical contacts from corroding.
- Protect the PS2000 power supply from dirt and foreign bodies.

5 Unpacking and installation



Caution – Electrical voltage!

Danger: 230 V and high voltage.

- Only electricians may connect the PS2000 power supply to the mains voltage supply and connect the plasma generator and HVC cable extension to the PS2000 power supply.

5.1 Unpacking

- Carefully open the PS2000 packaging. Note the information about directions provided on the packaging.
- Take the PS2000 out of the packaging.
- After removing, check in particular the rear power supply socket (#7, see page 8) to ensure that the O-ring is positioned correctly in the socket.

5.2 Installation requirements

Before installing the machine, the following points must be met:



- The machine must be fully intact.
- If the PS2000 communicates with a superordinate control unit, the PINs for the CAN bus connection must be assigned following the requirements in these operating instructions (see page 11).
- If installing as a permanent installation or in a building, a suitable switch or circuit breaker that satisfies national safety requirements (in Germany: VDE 0100) must be fitted as an upstream all-pole cut-off device that will disconnect the machine from the power supply. This cut-off device should be fitted near the machine and must be easily accessible to the user. The switch must also be labelled as the cut-off device for the machine.

5.2.1 Installing and starting up one single PS2000


The PS2000 can be mounted horizontally or vertically. Ensure a sufficient distance between the nearest housing wall and the ventilation slots (>150 mm).

To install the machine, perform the following steps in the specified order:

1. Mount the machine in a 19" control cabinet intended for this purpose. Only use the support rails on which the PS2000 is mounted to distribute the weight.
 - Use fixing bolts to secure the PS2000 in the bracket. Use the four slots in the front plate (#12) provided for this purpose.
 - Please ensure sufficient space between the control cabinet wall and front/rear (for electrical connections, dissipation of heat). This must not be any less than 150 mm.
2. Establish high-voltage connection between HVC cable extension and connection socket (#6) on the PS2000.
3. Mount an appropriate plasma generator. Make sure that the screw connection is hand tight.



4. Also earth the PS2000 at the earthing connection (#11; M5 thread).
5. Connect the PS2000 with the emergency stop circuit using the socket (#8).
6. Establish power supply to the PS2000 (#7).
 - 230 V / 50 Hz
Cable type: H05V 3x1.5 mm²
 Please ensure a safe electrical connection (especially PE conductor).
7. For control via a 24 V switching signal or bus communication, connect the communication line(s) and, if necessary, a terminator (#9; see page 11).




✓ The machine is installed.

5.2.2 Installing and starting up several PS2000s running in parallel

To install and start up several PS2000s which are controlled in parallel by one control unit, please proceed as follows:

1. Perform steps 1 – 6 for starting up an individual PS2000
2. For each PS2000, set a separate machine address on the rotary switch (#10).
3. Connect all PS2000s in series with the communication bus (#9).
Since there is a bus signal on both ports (X21&X22), you can connect the various PS2000s with one another. Make sure that a suitable cable is used for the connection between the PS2000s.



Terminator

Please ensure that the CAN bus cable is terminated at both ends by a terminator (120 ohms) (resistor configuration / PIN assignment: see page 11).

✓ The machines are installed.

6 Special notes on using the plasma process

6.1 General description

Treating surfaces with atmospheric plasma has several advantages. Examples include an increase in surface energy to achieve better surface wetting. Optimum surface wetting is the first and often most decisive step to achieving a good imprint, a uniform coating, a consistent coat of lacquer or an integrally bonded adhesive application. The bond at this boundary layer often determines the longevity and adhesive strength of this material pairing.

Atmospheric-pressure plasma increases throughput in many industrial processes, while at the same time saving the costs of solvents or chemical primers.

We have successfully integrated our plasma products into the following application fields:

- Ultra-fine cleaning of metal, glass and plastics
- Surface activation and surface functionalisation for optimised wettability
- Plasma-assisted laminating processes
- Plasma-assisted adhesive bonded joints
- Plugging and sealing
- Plasma-induced reduction of metal surfaces
- Chemical-free bleaching of textiles
- Treatment of food products to improve quality and shelf life
- Multi-component injection moulding

Practically all technical material classes can be efficiently processed under atmospheric pressure:

- Metals and metal alloys
- Plastics and composite materials
- Glass, ceramics, inorganic composites and natural stone
- Natural leather and synthetic leather
- Natural fibres, wood and paper

Since the plasma treatment is always just a single part of the entire process, it is important that the additional parameters are known in order to achieve an optimum result.

Typical influencing variables could be:

- Plasma process: distance from the substrate, speed, design of the modules
- Substrate/workpiece: material composition, contamination, electrical conductivity, thermal conductivity, moisture content
- Workpiece treatment: contamination before or after the plasma process, the time elapsed between the plasma process and the follow-up process

Additional information on applications, as well as publications, can be found on the website at www.relyon-plasma.com.

6.2 Carrying out surface treatment

Depending on the type and condition of your substrate, pre-cleaning before the plasma process can improve the overall outcome.

The effect of the treatment depends on the **working distance, treatment time, speed and consistency of movement, as well as the material to be treated.**

6.3 Measures to take after the surface treatment

To achieve an optimum result, it is important that as little time as possible elapses after the plasma treatment and that the treated surface is not touched or contaminated.

Cleaning the surface AFTER the plasma treatment is not recommended.

Since the workpiece may heat up depending on the type and duration of the plasma process, it may be necessary to allow the workpiece to cool down first before the next process step is executed. This is to ensure that the process will not be negatively impacted by the introduction of heat (e.g. in certain bonding processes).



Caution – Hot surface!

The workpiece to be treated may be heated up by the plasma process, depending on the process parameters. If necessary, allow the workpiece to cool down before handling it.

7

Operation

7.1

Controls / displays




Caution – Electrical voltage!

Danger of electric shock.


- Never reach into the area around the connected plasma generator while it is running or if it has shut down (e.g. to check why the plasma generator has shut down).

The PS2000 has a display (#3) on which the output values for plasma generation can be read. The display values appear one after the other in pairs with a display duration of 3 seconds each.



Display value	Function
Power	Electrical output in watts (W).
Frequency	Frequency at the high-voltage output in kilohertz (kHz).
Voltage	Output voltage in volts (V).
Current	Electrical current in milliamperes (mA).
Bit rate	Set CANopen baud rate in kilobits per second (Kbit/s).
Software version	Version of the installed software.

The PS2000 has LEDs indicating the current status.



No.	Display	Function
13	High Voltage	There is high voltage at the output of the connection socket (#6).
14	Error	There is an error present. It can be read off via the CAN bus. The PS2000 is not ready. The error must be acknowledged before the machine can be operated again.
15	Remote Control	Communication with superordinate control unit possible. The power supply cannot be switched on in this operating mode via the 24 V start signal. The “one push start” button on the front (#2; high voltage on/off) is not functional!

7.2 Switching on and operating the machine



Attention – Damage to machine!

The machine must only be operated with the plasma generator connected.

The plasma generator may be damaged if it is operated with no gas or too little gas.

- Never switch on the high voltage before sufficient gas is flowing through the plasma generator! Please comply with the information in the operating instructions for the plasma generator.

The machine can be switched on in three different ways:

- Manual switching of the machine using the “one push start” button (#2) on the front
- Communication via the 24 V switching signal
- CANopen bus communication

The switching signal of the “one push start” button and the 24 V switching signal are equivalent and can be used in parallel. However, to avoid operating errors during communication via the 24 V signal, in this case we recommend covering the button on the front with the protective flap and, if necessary, clearly labelling it as “not for use” with a sealing sticker.

When using bus communication, the “Remote control” LED (#15) lights up on the front. This deactivates the other two switch-on options.

7.2.1 Switching on and operating the machine using the “one push start” button

To switch on the PS2000 using the “one push start” button on the front, perform the following steps in the order given:

1. Switch the machine on using the master switch (#1).
➔ The master switch lights up green.
2. Ensure that a plasma generator is correctly connected to the PS2000 and that sufficient gas is flowing through the plasma generator.
3. Press the “one push start” button (#2; high voltage on/off).

✓ The machine is switched on.

If the machine is operated without bus communication, the electric parameters for plasma generation cannot be changed. When supplied, the PS2000 is operated with the following parameters: Frequency: 54 kHz, nominal output: 100%.

7.2.2 Switching on and operating the machine using the 24 V switching signal

To switch on the PS2000 using the 24 V switching signal, perform the following steps in the order given:

1. Switch the machine on using the master switch (#1).
➔ The master switch lights up green.
2. Ensure that a plasma generator is correctly connected to the PS2000 and that sufficient gas is flowing through the plasma generator.
3. Connect 24 V at PIN 1 to the plug X21 or X22 (GND is PIN 4).

✓ The machine is switched on.

If the machine is operated without bus communication, the electric parameters for plasma generation cannot be changed. When supplied, the PS2000 is operated with the following parameters: Frequency: 54 kHz, nominal output: 100%.

7.2.3 Switching on and operating the machine with bus communication

The PS2000 can be operated in bus communication mode in two ways:

- a. Via the “plasma control” software: This software is available from **Relyon Plasma GmbH** in the Downloads section of the website and is used to control an individual PS2000.
This software and the appropriate CAN/USB converter can be used to change and log operating parameters. Information about operating the PS2000 can be found in a separate data sheet supplied with the software.
- b. Via a control device produced by the customer. The CANopen protocol is based on the CIA301 specification. The object directory and linked information are described below.

7.2.4 CANopen object directory for control device

<i>Index (hex)</i>	<i>Sub-index (hex)</i>	<i>Name (reference)</i>	<i>Attribute</i>	<i>Data type</i>	<i>Default value</i>	<i>Comment</i>
Input						
2010	00	Status code	ro	UNSIGNED8	4	4,7,8: 4: Plasma off, 7: Plasma on, 8: Error
2020	00	Power actual	ro	UNSIGNED16		0..1045 (W)
2021	00	Frequency actual	ro	UNSIGNED8	54	40..65 (kHz)
2022	00	Voltage RMS actual	ro	UNSIGNED16	0	0..1500 (V)
2023	00	Current RMS actual	ro	UNSIGNED16		0..1000 (mA)
2050		Temperature				
	00	Highest sub-index supported	ro	UNSIGNED8		
	01	Temperature 1	ro	UNSIGNED8		0..90 (°C)
	02	Temperature 2	ro	UNSIGNED8		0..90 (°C)
	03	Temperature 3	ro	UNSIGNED8		0..90 (°C)
	04	Temperature 4	ro	UNSIGNED8		0..90 (°C)
2060	00	Power-On time	ro	UNSIGNED16		0..65535 (hours)
Output						
2000	00	Error status	rw	UNSIGNED8	0	0/1 (error reset with falling edge)
2030	00	High voltage	rw	UNSIGNED8	0	0/1 (0: Plasma off, 1: Plasma on)
2040	00	Power set	rw	UNSIGNED8	100%	75..100 (%) (minimum step width: 1%)
2041	00	Frequency set	rw	UNSIGNED16	54000	40000..65000 (Hz) (minimum step width: 1000 Hz)
2042	00	Voltage threshold	rw	UNSIGNED16	500 V	Internal error threshold – do not change!
2043	00	Current threshold	rw	UNSIGNED16	100 mA	Internal error threshold – do not change!

- Standard baud rate: 500 kbit/s. Baud rate can be changed via LSS protocol (defined using CIA305). Supported baud rates: 1 Mbit/s, 500 kbit/s, 250 kbit/s, 125 kbit/s.
- “Remote control” LED: To visualise communication via “Remote control”, the “Operational” status must be set once in the CANopen State Machine.

<i>Object</i>	<i>Index (hex)</i>	<i>Data (hex)</i>	<i>Comment</i>
All Nodes OPERATIONAL	0000	01 00 00 00 00 00 00 00	01 h Node ID (Node ID=0 → All Nodes)
Node 10 OPERATIONAL	0000	01 0A 00 00 00 00 00 00	01 h Node ID: 10 (10 d = 0A h)
All Nodes PREOPERATIONAL	0000	80 00 00 00 00 00 00 00	80 h Node ID (Node ID=0 → All Nodes)
Reset Node	0000	02 00 00 00 00 00 00 00	02 h Node ID (Node ID=0 → All Nodes))

- The communication status should be continuously monitored via the “Guard” or “Heartbeat” telegram! If there is no communication, the PS2000 must switch off the high voltage!

A complete CANopen object directory is available in the annex.



Attention – Safety!

We would highly recommend querying and monitoring the “Guard” or “Heartbeat” telegram so that the PS2000 can still be switched in the event of e.g. loss of communication with the superordinate control unit.



Attention – Damage to machine!

Please only change the approved parameters! If incorrectly actuated, the PS2000 may develop serious faults or be destroyed.

7.2.5 Error messages

Unexpected events are transmitted via the CANopen bus in the following form:

ID: 80h+NodeID data: 0x00 0xFF 0x81 0x yy 0x00 0x00 0x00 0x00

yy : Error code according to error status 1..15h

yy : 0x50 → Data received via RPDO is not within the valid range – valid parameters were adopted and invalid ones ignored.

The error codes have the following meanings:

Index (hex)	Error message	Comment
01h	Error: switching circuit central (Defective sensors / microcontroller)	Send in the plasma source for repair.
02h	Temperature: switching circuit central (insufficient cooling of the plasma source)	Check the cooling of the plasma source. Check whether fan is working / replace air filter (send plasma source in for repair if necessary).
03h	Error: auxiliary voltage 1 (DC voltage 1 for peripheral devices such as fans)	Send in the plasma source for repair.
04h	Intermediate circuit voltage (Defective sensors / microcontroller)	Send in the plasma source for repair.
05h	Error: controller (Defective sensors / microcontroller)	Send in the plasma source for repair.
06h	Error: auxiliary voltage 2 (DC voltage 2 for peripheral devices such as fans)	Send in the plasma source for repair.
07h	Is not used	
08h	Temperature of switching circuit central/PCB too high	Check the cooling of the plasma source. Check whether fan is working, replace air filter if necessary (send plasma source in for repair if necessary).
09h	Communication with controller interrupted (CAN bus error. Bus offline)	Check communication / cabling.
10h	PFC error (PFC microcontroller defective)	Send in the plasma source for repair.
11h	Emergency stop actuated	Check whether the emergency stop is properly connected / cable breakage.
12h	Is not used	

13h	Output voltage too low (Plasma does not ignite; PG31 goes into short circuit)	Check whether sufficient gas is available. Check the PG31 for damage.
14h	Overvoltage (Plasma does not ignite; arc cannot be formed)	Check whether too much gas is set. Check the PG31 for damage.
15h	Error: fan	Check whether fan is working; replace air filter if necessary.

7.2.6 “Burn in” set of parameters

The PS2000 comes with a preset set of parameters:

Power set: 100, Frequency set: 54000, Voltage threshold: 500, Current threshold: 100

It is possible to change the parameters, but they are reset to their “Burn in” values as soon as the machine is restarted. A permanent change to the “Burn in” parameters can only be made by the manufacturer (**Relyon Plasma GmbH**).



Attention – Damage to machine!

Do not change the threshold values (voltage / current threshold) for the “Burn in” parameters! If incorrectly actuated, the PS2000 may develop serious faults or be destroyed.

7.3 Switching off the machine

To switch off, perform the following steps in the order given:

1. Switch off plasma generation.
2. Switch the machine off using the master switch (#1).

✓ The machine is switched off.

7.4 Error acknowledgement

When the PS2000 reports an error (error LED lights up), the reason for the error message can be read via the CAN bus interface (error code).

Potential troubleshooting steps are described in section 10.

Once the cause of the error has been remedied, the error message can be acknowledged. There are two ways of doing this:

- a) Operation without bus communication: Switch off the PS2000 at the master switch and switch on again approximately 5 seconds later. The error is acknowledged.
- b) Operation with bus communication: Acknowledge the error using the control software provided or by acknowledging the error status: Enter “0x00” in the object index 0x2000/00 (falling edge).

8 Taking out of service



Caution – Electrical voltage!

Danger: 230 V and high voltage.

- Only electricians may disconnect the power supply, plasma generator or HVC cable extension from the PS2000 power supply.



Caution – Electrical voltage!

Danger due to high voltage at output.

- After switching off the high voltage / supply voltage, there may still be high voltage on the output for up to 1 second. Please be aware of this whenever working on the PS2000, high-voltage cable and plasma generator.

To take the machine out of service, perform the following steps in the order given:

1. Switch the machine off using the master switch (#1).
2. Disconnect the PS2000 from the mains voltage supply: Disconnect the power connector (#7).
3. Remove the HVC cable extension and the plasma generator.
4. Remove the PS2000 power supply.

✓ The machine is out of service.

9 Maintenance and cleaning

9.1 Maintenance



Caution – High voltage! Danger of death!

High voltage is produced in the PS2000 power supply's power pack. This voltage is still present after the machine is switched off.

- It is forbidden to open the machine.
- Whenever undertaking maintenance or repair work on the PS2000 or its connected components, always disconnect the power supply to the PS2000.



Attention – Damage to machine!

Opening the machine may cause it to be damaged.

- It is forbidden to open the machine.


With the exception of the dust filters used, the machine requires no maintenance.

Replace the filter mat at least every 5000 operating hours. If working in environments with high levels of dust, they may have to be replaced sooner. You can source the filter mats needed as spare parts from

Relyon Plasma GmbH.

To change the dust filters, proceed as follows:

1. Disconnect the power supply to the PS2000.
2. Open the ventilation grille by loosening the screw stated (#16).
3. Take out the old dust filter and insert a new one (class G2 coarse dust filter).
4. Screw the ventilation grille with the new filter to the PS2000.



9.2 Cleaning

Only clean the outside of the PS2000 power supply.

- The PS2000 power supply must be switched off and disconnected from the mains voltage supply.
- Only dry clean the PS2000 power supply.

10 Troubleshooting

10.1 Overview of faults / errors

Fault / error	Cause	Rectification
Master switch (#1) does not light up	Fuse defective.	Fuse in machine must be changed. Contact customer service.
	Power connector incorrectly connected.	Check the mains unit connection.
	No / incorrect voltage supply.	Check the mains voltage supply.
“Error” LED (#14) lit up	There is an error, the machine is not ready.	Read out (CAN bus), rectify and acknowledge the error. Without CAN bus communication, switch the PS2000 off, wait 5 seconds then switch it back on.
		De-energise the machine. Switch on again.
		Problem cannot be fixed: Contact customer service.
Even though the 24 V start signal is present, plasma is not being ignited at the plasma generator.	“Remote control” LED (#15) lit up.	The machine is controlled via the CAN bus. Operation via the 24 V start signal is not possible in this operating mode.
	“Error” LED (#14) lit up	See error message for “Error LED lit up”.
		Check whether there is a sufficient flow of gas in the permissible range through the connected plasma generator (see the data sheet for the nozzle used or operating instructions for the PG31 plasma generator). Check that the HV cable and gas supply pipe are correctly connected, and are undamaged and not buckled.
The plasma cannot be stopped in 24 V mode or in manual mode.	Both switch-on signals are present	If both switch-on signals are applied by mistake, the plasma can only be stopped by removing both signals (see section 7.2).
Parasitic discharge (discharge at undesired points, e.g. at plasma generator cable connector)	Machine or high-voltage cable damaged	Take the machine out of operation and contact customer service.
Flashover (e.g. on machine parts)	Faulty earth connection	Check that all earth connections have been established correctly.

If the machine is not working properly, return it to **Relyon Plasma GmbH** to be checked.

11 Environment

11.1 Disposal



Be mindful of the environment.

Used electrical and electronic equipment must not be disposed of along with normal waste.

- The machine contains valuable materials that can be recycled. Take the machine to a suitable collection point.

12 CE conformity



We declare that this product conforms to CE standards.

The product name is to be found on the name plate on the back of the housing. The declaration of conformity can be viewed in the Downloads section of the **Relyon Plasma** website.

13 Spare parts

Item number	Description
79134200	Filter mat

Relyon Plasma GmbH
A TDK Group Company

Osterhofener Strasse 6
93055 Regensburg
Germany

Phone: +49-941-60098-0

Fax: +49-941-60098-100

E-mail: info-relyon@tdk.com

<https://www.relyon-plasma.com>

Annex: Complete CANopen object directory

Index (hex)	Sub-index (hex)	Name (reference)	Attribute	Mappable	Object type	Data type	Default value	Comment
1000	00	Device type	ro	n	VAR	UNSIGNED32	0x00000000	
1001	00	Error register	ro	y	VAR	UNSIGNED8	0x00	See "Error message"
1003		Pre-defined error field			ARRAY	UNSIGNED32		
	00	Number of errors	rw	n		UNSIGNED8	00 _h	
	01	Standard error field	ro	n		UNSIGNED32	0000 0000 _h	
	02	Standard error field	ro	n		UNSIGNED32	0000 0000 _h	
	03	Standard error field	ro	n		UNSIGNED32	0000 0000 _h	
	04	Standard error field	ro	n		UNSIGNED32	0000 0000 _h	
1005	00	COB-ID SYNC message	rw	n	VAR	UNSIGNED32	0000 0080 _h	
1008	00	Manufacturer device name	ro	n	VAR	VISIBLE_STRING	"PS2000"	
1009	00	Manufacturer hardware version	ro	n	VAR	VISIBLE_STRING	hardware version string,	
100 A	00	Manufacturer software version	ro	n	VAR	VISIBLE_STRING	software version string, e.g. "V01.00"	
100C	00	Guard time	rw	n	VAR	UNSIGNED16	0000 _h	0..32000 [ms]
100D	00	Life time factor	rw	n	VAR	UNSIGNED8	00 _h	0..255 [factor] for guard time
1010		Store parameters			ARRAY	UNSIGNED32		
	00	Highest sub-index supported	ro	n		UNSIGNED8	04 _h	
	01	Save all parameters	rw	n		UNSIGNED32	0000 0001 _h	Ascii "save" Complete object directory (incl. 2040 – 2043) is saved
	02	Save communication parameters	rw	n		UNSIGNED32	0000 0000 _h	"save" not supported
	03	Save application parameters	rw	n		UNSIGNED32	0000 0000 _h	"save" not supported
	04	Save manufacturer defined parameters	rw	n		UNSIGNED32	0000 0001 _h	"Burn in" set of parameters – Only objects 2040 – 2043 are saved
1011		Restore parameters			ARRAY	UNSIGNED32		
	00	Highest sub-index supported	ro	n		UNSIGNED8	00 _h	
	01	Restore all parameters	rw	n		UNSIGNED32	0000 0001 _h	Ascii "load" Complete object directory (<u>not including</u> 2040 – 2043) is deleted.
	02	Restore communication parameters	rw	n		UNSIGNED32	0000 0000 _h	"load" not supported
	03	Restore application parameters	rw	n		UNSIGNED32	0000 0000 _h	"load" not supported

Index (hex)	Sub- index (hex)	Name (reference)	Attribute	Mappable	Object type	Data type	Default value	Comment
	04	Restore manufacturer defined parameters	rw	n		UNSIGNED32	0000 0001 _h	"Burn in" set of parameters is reset to factory settings
1014	00	COB-ID emergency message	rw	n	VAR	UNSIGNED32	80 _h + node ID	
1016		Consumer heartbeat time			ARRAY			
	00	Highest sub-index supported	ro	n		UNSIGNED8	03 _h	
	01	Consumer heartbeat time	rw	n		UNSIGNED32	0000 0000 _h	0..32000 [ms]
	02	Consumer heartbeat time	rw	n		UNSIGNED32	0000 0000 _h	0..32000 [ms]
	03	Consumer heartbeat time	rw	n		UNSIGNED32	0000 0000 _h	0..32000 [ms]
1017	00	Producer heartbeat time	rw	n	VAR	UNSIGNED16	0000 _h	
1018		Identity object			RECORD	IDENTITY		
	00	Highest sub-index supported	ro	n		UNSIGNED8	04 _h	
	01	Vendor ID	ro	n		UNSIGNED32	0000 0000 _h (Bosch Rexroth AG Pneumatics – ship engineering)	
	02	Product code	ro	n		UNSIGNED32	0000 0000 _h	
	03	Revision number	ro	n		UNSIGNED32	0000 0000 _h	
	04	Serial number	ro	n		UNSIGNED32	FFFF FFFF _h	
1200		SDO server 1 parameter			RECORD	SDO_PARAMETER		
	00	Highest sub-index supported	ro	n		UNSIGNED8	02 _h	
	01	COB ID client -> server (rx)	ro	n		UNSIGNED32	0000 0600 _h + Node ID	
	02	COB ID server -> client (tx)	ro	n		UNSIGNED32	0000 0580 _h + Node ID	
1400		RPDO 1 comm. parameter			RECORD	PDO_COMMUNICATION_PARAMETER		
	00	Highest sub-index supported	ro	n		UNSIGNED8	02 _h	
	01	COB ID used by RPDO	rw	n		UNSIGNED32	0000 0200 _h + Node ID	
	02	Transmission type	rw	n		UNSIGNED8	FF _h	"FF" asynchronous; "1" synchronous See CIA301
1600		RPDO 1 mapping parameter			RECORD	PDO_MAPPING		
	00	Number of mapped application objects in RPDO	ro	n		UNSIGNED8	Number of mapped objects (digital outputs)	5

Index (hex)	Sub-index (hex)	Name (reference)	Attribute	Mappable	Object type	Data type	Default value	Comment
	01	1 st application object	ro	n		UNSIGNED32	2030 00 08	
	02	2 nd application object	ro	n		UNSIGNED32	2040 00 08	
	03	3 rd application object	ro	n		UNSIGNED32	2041 00 10	
	04	4 th application object	ro	n		UNSIGNED32	2042 00 10	
	05	5 th application object	ro	n		UNSIGNED32	2043 00 10	
1800		TPDO 1 comm. parameter			RECORD	PDO_COMMUNICATION_PARAMETER		
	00	Highest sub-index supported	ro	n		UNSIGNED8	05 _h	
	01	COB ID used by TPDO	rw	n		UNSIGNED32	0000 0180 _h + Node ID	
	02	Transmission type	rw	n		UNSIGNED8	FF _h	
	03	Inhibit time	rw	n		UNSIGNED16	0000 _h	See CIA301 0..32000 [ms]
	05	Event timer	rw	n		UNSIGNED16	0000 _h	See CIA301 0..32000 [ms]
1A00		TPDO 1 mapping parameter			RECORD	PDO_MAPPING		
	00	Number of mapped application objects in TPDO	ro	n		UNSIGNED8	Number of mapped objects (digital inputs)	5
	01	1 st application object	ro	n		UNSIGNED32	2010 00 08	
	02	2 nd application object	ro	n		UNSIGNED32	2020 00 08	
	03	3 rd application object	ro	n		UNSIGNED32	2021 00 10	
	04	4 th application object	ro	n		UNSIGNED32	2022 00 10	
	05	5 th application object	ro	n		UNSIGNED32	2023 00 10	
1F51		Program control			Array	UNSIGNED8		
	00	Highest sub-index supported	ro	n		UNSIGNED8	1	
	01	Program 1	rw	n		UNSIGNED8		Internal use – do not change!

2000	00	Error status	rw	n	VAR	UNSIGNED8		0 Rw: Delete error statuses, see "Error message"; RPDO2; Byte1
2010	00	Status code	ro	j	VAR	UNSIGNED8		See "Status code"; TPDO1; Byte1
2020	00	Power actual	ro	j	VAR	UNSIGNED16		TPDO1; Byte3,4
2021	00	Frequency actual	ro	j	VAR	UNSIGNED8		TPDO1; Byte2
2022	00	Voltage RMS actual	ro	j	VAR	UNSIGNED16		TPDO1; Byte5,6

Index (hex)	Sub- index (hex)	Name (reference)	Attribute	Mappable	Object type	Data type	Default value	Comment
2023	00	Current RMS actual	ro	j	VAR	UNSIGNED16		TPDO1; Byte7,8
2030	00	High voltage	rw	j	VAR	UNSIGNED8	Write: 0/1 Read: Corresponding status code 0x2010 (PlasmaOk)	RPDO1; Byte1
2040	00	Power set	rw	j	VAR	UNSIGNED8		0..100; RPDO1;Byte2
2041	00	Frequency set	rw	j	VAR	UNSIGNED16		RPDO1; Byte3,4
2042	00	Voltage threshold	rw	j	VAR	UNSIGNED16		Internal error threshold – do not change! RPDO1; Byte5,6
2043	00	Current threshold	rw	j	VAR	UNSIGNED16		Internal error threshold – do not change! RPDO1; Byte 7,8
2050		Temperature			Array			
	00	Highest sub-index supported	ro	n		UNSIGNED8	5	
	01	Temperature 1	ro	n		UNSIGNED8		TPDO2; Byte3
	02	Temperature 2	ro	n		UNSIGNED8		TPDO2; Byte4
	03	Temperature 3	ro	n		UNSIGNED8		TPDO2; Byte5
	04	Temperature 4	ro	n		UNSIGNED8		TPDO2; Byte6
	05	Temperature 5	ro	n		UNSIGNED8		
2060	00	Power-On time	ro	n	VAR	UNSIGNED16		TPDO02; Byte1,2
2100	00	Internal use	wo	n	VAR	UNSIGNED32		Do not change!
2110	00	Internal use	ro	n	VAR	UNSIGNED16		